Cultural Resour	ED CUNDIA FARM
	1. D. NUMBER M-36-L6
CLACKAMAS COUNTY	M-30-10
PHOTO INFORMATION: ROLL: VII FRAME: 9, 10, 11	STUDY AREA. Milwaukie
ROLL: VII	166AL: /. 1 K. 1E UEC. 36CB
FRAME: 9, 10, 11	7005 PT-1 5/25 11
	WITE
IDENTIFICATION:	
common/HISTORICAL name: Pioneer - Fai.	ling House (Henry)
ADDRESS: 2515 S.E. Lake Rd.	AREA: Milwaukie
CURRENT OWNER: ROBERT HAWKINS	USE: Residence
/ Cama	
ORIGINAL OWNER; HENRY FAILING AREA OF SIGNIFICANCE; TOWN; X COL	USE; Residence
AREA OF SIGNIFICANCE: TOWN: X COU	ONTY: CITY: NATION:
A 11 Comments and 1 or 1 and 1 mayor or 1	
HISTORIC INTEREST:	nate.
THEME: 19th Century.	DATE: 1858
OBSCRIPTION: Henry Failing built this on Taylor Street in downtown Portland. In 18	nouse and it stood between oth & oth Streets
on Taylor Street in downtown Portland. In 18 it stood on the bank of Kellogg Lake, across	
1914 Isabella Holt moved it to its current lo	cation and restored it in the late 1960's.
LaGrande lived in this house (1909); The Down	as family owned the home from 1937-1960.
neorande iivee in this notice (1707), inc bown	
ARCHITECTURAL INTEREST:	
	STORIES: 11/2
DATE: 1850 CONDITION: Good	STORIES: 1½ ARCHITECT:
SIDING: 8" shiplap, corner decorative ra	ke boards, patterned (3 styles)
ROOF: Cross gable w/central truneated	hip - turned balustrade & posts "widow's walk"
pooks: Paneled w/single pane of glass,	flash glass surrounds transom
WINDOWS: Architrave molding - 1st narro	w 1/1, shutters
MAIN ENTRANCE:	and Jaconstina spindlersont breakers
MAIN ENTRANCE: Minor entrance: flat Major entrance: encircling porch, decorative	
major entrance: encircling porch, decorative glass transom (south elev port hole window	
1075: Square nails, decorative chimney	
Dystate manage stocked to containing	
540	37,44
	,
P q	
	BIBLIOGRAPHY:
	1011001011111
	A STATE OF THE STA
Notice to the second se	
	1
	DATE: 9/22/83
	RECORDER: Hayden, Altier





